


0033

Existing Short Section

Stable Section Existing

1:50@A3







Note: Building needs full refurbishment. The dilapidated timber pergola is unsafe and rotten. The windows and doors need full refurbishment. The building is also fully overgrown.

P0 2020-10-27 Planning Issu Revision Date Description 2020-10-27 Planning Issue

© copyright Wimshurst Pelleriti, all rights reserved 2020

Do not scale-off this drawing. Wimshurst Pellertil take no responsibility for any dimensions obtained by measuring or scaling from this drawing and no reliance may be placed on such dimensions, if no dimension is given, it is the responsibility of the recipient to ascertain the dimension specifically from the Architect or by site measurement.

The sizing of all structural and service elements must always be checked against the relevant engineers drawings. No reliance should be placed upon sizing information shown on this drawing.

Р	roject	
	1441 -	

Little Forest Folk | Morden Lodge

Drawing Title

Existing Section Stable

WP-0739-A-0033-S-XX 2020-10-27 Scale @ A3 Revision Date 1: 50 P0 Drawing Purpose

PLANNING

WIMSHURST PELLERITI

0208 780 2206 Info@wp.uk.com wimshurst-pelleriti.com



This page is intentionally left blank