

APPENDIX 4

SEVERITY SLIGHT	District Merton Ref.No 15VW40385	Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2016'	Grid Reference 524310 / 171150 Police Officer Attend: Yes
Date 29/08/2015 Day Saturday Time 13:49 Weather Fine without high winds Road Surface Dry Street Lighting Daylight	Road U Location Nfl: Belvedere Grove 45M Sw J/W Belvedere Avenue Description V1 left with Engine Running , no Driver, left Road, Collided V2 and House Wall of Accident		
SITE DETAILS Speed Limit 30 MPH Carriageway Single carriageway Junction Detail Not at or within 20 metres of junction Junction Control 2nd Road Number Pedestrian Facilities None within 50 metres No physical crossing facility within 50 m		SPECIAL SITE CONDITIONS None CARRIAGEWAY HAZARDS None	CONTRIBUTORY FACTORS 410 Loss of control (Driver/Rider - Error) PARTICIPANT PROBABILITY Vehicle 001 A
VEHICLES INVOLVED 2		CASUALTIES INVOLVED 1	
Veh.No. 1 Vehicle type Car Make Model Manoeuvre Going ahead right hand bend Veh. direction from Northeast to Northwest Towing? No tow or articulation Skidded No skidding, jack-knifing or overturning Veh location at impact (restricted lane) On main carriageway not in restricted lane Junct. location of veh. at 1st impact Not at or within 20m of junction Veh left carriageway? Left carriageway nearside Hit object in c'way? Parked vehicle Hit object off c'way? Other permanent object First point of impact Front Veh registration no. Other veh.hit (ref.no) 2 Hit and run Not hit and run Drivers age 49 yrs Sex Male Breath test Not provided (medical r Driving Lic Left Hand Drive Unknown Foreign veh. Not foreign registered vehicle Journey purpose Other Post code SW20		Cas No 1 Cas Class Pedestrian Veh ref No 1 Severity SLIGHT Age 49 yrs Sex Male Post code SW20 Car Passenger? Not a passenger PSV Passenger? Not a passenger Seat Belt 8 Cycle Helmet Ped Movement Unknown or other Ped Location On footway or verge Ped Direction to Standing still School Pupil Other Roadworker injured Not applicable	
Veh.No. 2 Vehicle type Car Make Model Manoeuvre Parked Veh. direction from Parked to Parked Towing? No tow or articulation Skidded No skidding, jack-knifing or overturning Veh location at impact (restricted lane) On main carriageway not in restricted lane Junct. location of veh. at 1st impact Not at or within 20m of junction Veh left carriageway? Did not leave carriageway Hit object in c'way? None Hit object off c'way? None First point of impact Front Veh registration no. Other veh.hit (ref.no) 1 Hit and run Not hit and run Drivers age ? yrs Sex Male Breath test Driver not contacted Driving Lic Left Hand Drive Unknown Foreign veh. Not foreign registered vehicle Journey purpose Other Post code Unknown		Other Details	
Full Details		06-October-2016 Accident Ref.No 15VW40385	

Page 87

This page is intentionally left blank